From: "Young, Howard S." <younghs@cdmsmith.com>
To: "Sheldrake, Sean" <sheldrake.sean@epa.gov>

"Zhen, Davis" <Zhen.Davis@epa.gov>

CC: "Scott Coffey" <coffeyse@cdmsmith.com>

"Trump, Julee M." <trumpjm@cdmsmith.com>
"Greazel, Andrew" <GreazelAD@cdmsmith.com>

Date: 4/6/2018 3:50:48 PM

Subject: RE: Daily status report April 5, 2018, Pre-Remedial Design Investigation and Baseline

Sampling, Portland Harbor Superfund Site delib

Sean.

So far all of the samples have been collected at their prescribed stratified random sample location and no contingency alternate locations (Alternate Location 1, 2 etc.) were used. They did have to resort to the contingency 50-foot radial distance contingency on 4/3 due to poor recovery within the 25-foot radius per the FSP. We will make sure to track and update you if any alternate stratified random locations are implemented.

Howard S. Young, LG | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007-6493

T: 425.519.8300 | Direct 425.519.8351 | Cell 206.491.4663 | younghs@cdmsmith.com | www.cdmsmith.com

----Original Message-----

From: Sheldrake, Sean [mailto:sheldrake.sean@epa.gov]

Sent: Friday, April 06, 2018 12:39 PM

To: Young, Howard S. <younghs@cdmsmith.com>; Zhen, Davis <Zhen.Davis@epa.gov>

Cc: Coffey, Scott < CoffeySE@cdmsmith.com>; Trump, Julee M. < trumpjm@cdmsmith.com>; Greazel,

Andrew < Greazel AD@cdmsmith.com>

Subject: RE: Daily status report April 5, 2018, Pre-Remedial Design Investigation and Baseline

Sampling, Portland Harbor Superfund Site delib

Thanks Howard, so thus far, no issues with taking the sample in the exact spot prescribed in the random stratified? Would ike updates when they have to go to the backup locations if possible.

S

Sean Sheldrake RPM, Unit Diver Officer

U.S. Environmental Protection Agency

1200 Sixth Avenue, Suite 155, M/S DOC-01 Seattle, WA 98101

206.553.1220 desk

206.225.6528 cell

https://urldefense.proofpoint.com/v2/url?u=https-3A www.epa.gov scientific-

2Ddiving&d=DwIFAg&c=NpiPIT1KNSO0vXgGk6ogJQ&r=NT5-

VWbPIXC048GFn4E6tWt8tvpGnOtsN7 n1CVeouA&m=BAJgDSQEs2SNJOiIZ2pXL9WO9f2av-

jjeq3GFD-g2Ak&s=vtlXzN890mWssoTxDYsbv1z6ZKq-pvnYJjpjdDofK0s&e=

https://urldefense.proofpoint.com/v2/url?u=https-3A www.facebook.

com EPADivers&d=DwIFAg&c=NpiPIT1KNSO0vXgGk6ogJQ&r=NT5-

VWbPIXC048GFn4E6tWt8tvpGnOtsN7 n1CVeouA&m=BAJgDSQEs2SNJOiIZ2pXL9WO9f2av-

jjeq3GFD-g2Ak&s=U08qDmGQpWwVOMdip7DRyay YlljBws0ZWxf1DZg6cs&e=

https://urldefense.proofpoint.com/v2/url?u=https-3A__www.epa.gov_superfund_portland-2Dharbor&d=DwlFAg&c=NpiPIT1KNSO0vXgGk6ogJQ&r=NT5-VWbPIXC048GFn4E6tWt8tvpGnOtsN7_n1CVeouA&m=BAJgDSQEs2SNJOilZ2pXL9WO9f2avjjeq3GFD-g2Ak&s=L Rv0sl5ye TlVddUi08XlqrLfWlbBi9vK44QpMQlSk&e=

----Original Message-----

From: Young, Howard S. [mailto:younghs@cdmsmith.com]

Sent: Friday, April 6, 2018 12:14 PM

To: Sheldrake, Sean <sheldrake.sean@epa.gov>; Zhen, Davis <Zhen.Davis@epa.gov>

Cc: Scott Coffey <coffeyse@cdmsmith.com>; Trump, Julee M. <trumpjm@cdmsmith.com>; Greazel,

Andrew < Greazel AD@cdmsmith.com>

Subject: Daily status report April 5, 2018, Pre-Remedial Design Investigation and Baseline Sampling,

Portland Harbor Superfund Site

Sean and Davis,

Attached is the daily report for the oversight of the surface sediment sampling on Thursday. Surface sediment sampling will continue throughout the weekend and we are planning to resume oversight on Monday.

Please contact me if you have any questions.

Howard S. Young, LG | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007-6493

T: 425.519.8300 | Direct 425.519.8351 | Cell 206.491.4663 | younghs@cdmsmith.com | http://www.cdmsmith.com